

2013 BMW X5



Summary

I started my inspection of this vehicle with the exterior. Upon first glance, the car sits nicely on the suspension and all four wheels. I then went around the vehicle to look for any imperfections. First thing I noticed was that the front bumper cover had rock chips on it. Also they were slight scratches along the lower portion of the panels but very minimal and normal for the year & make. There was minimal scratch marks on the rims and the tires were in good condition.

I then moved to the interior of the vehicle. The interior was in good shape. No cuts or tears on any of the leather seats or carpet flooring area. The floor mats were located in the rear trunk area of the vehicle along with the full-size spare tire. All electronic components such as the heat, air conditioning and backup camera worked as they should during this time of inspection.

I then took the vehicle out for a test drive. I got the vehicle up to approximately 55 mph on the highway. The car drove straight and true. The engine and transmission performed quite nicely. The engine had a good deal of power and the transmission shifting smoothly. I felt no vibrations or pulsations coming from the braking system. See below and pictures for more info.

Vehicle Information

Year	2013
Make	BMW
Model	X5
VIN	5uxzw0c56d0b95395
Stock No.	85
Mileage	133045
Engine Cylinders	6 Cylinder
Exterior Color	Blue
Interior Color	Brown
Interior Material	Leather
Fuel Type	Diesel

Drivetrain

Transmission	Automatic
Drive Type	All Wheel Drive

Road Test

Road Test	 Good
Engine Starting Easily	 Good
Engine running well after Started	 Good
Transmission performance	 Good
Differential Performance	 Good
Transfer Case Performance	 Good
Wheel Bearing Performance	 Good
Braking Performance	 Good
Suspension Performance	 Good
Steering Performance and Alignment	 Good
Tire Pressure System (TPMS)	 Good

Exterior

Back-Up Camera	 Good
Wiper Blades	 Good
Windshield Washer	 Good
Body Panel Alignment	 Good
Scratches	 Issues
The front bumper has scratches to the underside. Need to be under the vehicle to see these. There are minor misc scratches around the vehicle. Normal for mileage and most too small to see in photos.	
Paint Condition	 Issues
The paint shows some wear and tear that is consistent with age and mileage.	
Seals	 Good
Rust	 Issues
The underside shows areas of minor surface rust. See pictures.	
Exterior Lights	 Good
Power Sunroof	 Good
Power Door Mirrors	 Good
Bumpers	 Issues
Rock Chips on the front bumper	
Side Moldings	 Good
Underbody/Frame Condition	 Good
Glass	 Good
Dings	 Good
Dents	 Good

Interior

Steering Wheel	 Good
Horn	 Good
Cruise Control	 Good
Seat Condition	 Issues
There is light wear to the seats. Normal for mileage.	
Heated Seats	 Good
Seat Belts	 Good
Clock	 Good
Radio/Navigation/DVD	 Good
Inner Door Panels	 Issues
The inner door panels show wear consistent with age and mileage.	
Power Locks	 Good
Power Window Switches	 Good
Center Console	 Good
Dash	 Good
Dash Lights Working	 Good
Air Conditioning	 Good
Heater	 Good
Rear Defroster	 Good
Carpet	 Issues
The carpet shows normal wear consistent with age and mileage.	
Floor Mats	 Good
Signs of Smoking?	 Good
Cup Holders	 Good
Headliner	 Good
Blower Motor	 Good
Instrument Cluster/Gauges	 Good
Unusual Odors	 Good
Window Function	 Good
Interior Trim	 Issues

The interior trim shows normal wear consistent with

THE INTERIOR TRIM SHOWS NORMAL WEAR CONSISTENT WITH
age and mileage.

Sun Visors



Good

Mechanical

Air Filter	 Good
Battery Condition	 Good
Charging System	 Good
Cooling Fan Condition Mechanical/Electronic	 Good
Hoses and Clamps Age/Cracking	 Good
Radiator Condition	 Good
Engine Coolant Condition	 Good
Belts	 Good
Power Steering System	 Good
Power Steering Fluid Condition	 Good
Engine Oil Condition	 Good
Engine Oil Leaks	 Good
Transmission Fluid Condition	 Good
Transmission Fluid Leaks	 Good
Brake System Condition	 Good
Brake Fluid Leaks	 Good
Transfer Case Leaks	 Good
Differential leaks	 Good
Muffler System	 Issues
Exhaust shows some slight surface rust throughout, but at this time has no leaks and sounds good.	
CV Boots and Joints	 Good
Shocks and bushings Condition. Leaking?	 Good
Ball Joints and Tie Rods	 Good
Radiator Cap Sealing Properly	 Good
Coolant Leaks	 Good

Tire / Wheels

Manufacturer	
Driver's Front Tire	Continental
Passenger's Front Tire	Continental
Driver's 1st Axle Outer Tire	Continental
Passenger's 1st Axle Outer Tire	Continental
Size	
Driver's Front Tire	255/55/ZR18
Passenger's Front Tire	255/55/ZR18
Driver's 1st Axle Outer Tire	255/55/ZR18
Passenger's 1st Axle Outer Tire	255/55/ZR18
Tire Condition	
Driver's Front Tire	No Issues
Passenger's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues
Wheel Condition	
Driver's Front Tire	No Issues
Driver's 1st Axle Outer Tire	Scratches
Passenger's Front Tire	No Issues
Passenger's 1st Axle Outer Tire	Scratches
Tire Tread	
Driver's Front Tire	11/32
Passenger's Front Tire	11/32
Driver's 1st Axle Outer Tire	11/32
Passenger's 1st Axle Outer Tire	11/32
Spare Tire	
	Yes

Vehicle Images































































































































































































MFD BY BAYERISCHE MOTOREN WERKE AG

06/2013

GVWR	6261 lbs	2840 kg	TIRE / RIM	
GAWR FRONT	2976 lbs	1350 kg	WITH 255/55 R18	18.5J x 18
GAWR REAR	3483 lbs	1580 kg	WITH 255/55 R18	18.5J x 18

THIS VEHICLE CONFORMS TO ALL APPLICABLE U. S. FEDERAL
MOTOR VEHICLE SAFETY STANDARDS IN EFFECT ON THE DATE
OF MANUFACTURE SHOWN ABOVE.

5UXZW0C56D0B95395 TYPE: MPV



A76M

7 320 729